

Product / Process Change Notice

Parts Affected:

Surface mount, bridge rectifiers manufactured in the HD DIP epoxy molded case.

Extent of Change:

The marking code on the device will no longer include the manufacturing lot code.

Reason for Change:

The manufacturing lot code is traceable by the manufacturing lot # and is not required to be marked on individual devices.

Effect of Change:

The two digit lot code has been removed from the individual devices.

Example: CBRHD-01 marking with lot code:

**CEN79
CBD1**

CBRHD-01 marking without lot code:

**CEN
CBD1**

Effective Date of Change:

January 1, 2009

Part #'s Affected:

CBRHD-01
CBRHD-02
CBRHD-04
CBRHD-06
CBRHD-10
CBRHDSH1-60
CBRHDSH1-100
CBRHDSH1-40L
CBRHDSH2-40
CBRHDSH2-100