

## Process Change Notice

**Parts Affected:**

All Bridge Rectifiers in the SMDIP package.

**Extent of Change:**

Reduced thickness (height) of the epoxy body.

**Reason for Change:**

To provide a lower profile package.

**Effect of Change:**

No effect except for reduced height. No change in Mounting Pads required.

**Effective Date of Change:**

First quarter of 2002.

**Sample Availability:**

Please contact Salesperson or Manufacturer's Representative.

**Figures:**




Figure 1. Present Package




Figure 2. New Package



**Figure 3. Comparison of Present and New Packages**

**Part Numbers Affected:**

**CBR1-D010S  
CBR1-D020S  
CBR1-D040S  
CBR1-D060S  
CBR1-D080S  
CBR1-D100S  
CBR1F-D020S  
CBR1F-D040S  
CBR1F-D060S  
CBR1U-D010S  
CBR1U-D020S**